

NO. 700  
 NO. 6259346  
 D.D. 1-6-83  
 BY L. C. Chabon  
 DATE 1/6/83

R# C1224  
 PT. N.  
 MFD. 7-69

COMMENTS:

6-20-83

THIS GUN WAS COCKED, ITS SAFETY WAS SWITCHED TO THE POSITION, AND IT WAS PLACED INSIDE A COLD BOX (INSIDE THERMOMETER INDICATED -30 F) AT 4:35 a.m. ON 06 APRIL 83. UPON REMOVAL OF THIS GUN FROM THE COLD BOX (INSIDE THERMOMETER READ -29 F) AT 9:40 a.m. ON 07 APRIL 83, THE FOLLOWING WAS IMMEDIATELY PERFORMED:

① Pull trigger to see if it kinds or sticks back —  
 IT DID NEITHER.

② Switch safety to "F" position — IT DID NOT FIRE-DOWN.

③ Drop bolt and check for jam — NONE.

④ Check bolt and work handle — NO PROBLEM, POSITIVE ACTION.

⑤ Switch safety to "S" position, pull back hard on trigger, release trigger, switch safety to "F" position. Repeat this three times. — THE FIRING PIN DID NOT FIRE-DOWN.

⑥ With safety switched to "F", pull trigger. — THE FIRING PIN FIRED-DOWN. SNAPPY.

⑦ Rack the bolt and repeat the entire test. — No PROBLEMS ENCOUNTERED AND NO F.S.R. OBSERVED.

⑧ Perform "trick test". — GUN PASSED THE "TRICK TEST".

|   |   |   |   |   |   |   |   |   |   |
|---|---|---|---|---|---|---|---|---|---|
| ( | ( | ( | ( | ( | ( | ( | ( | ( | ( |
| ) | ) | ) | ) | ) | ) | ) | ) | ) | ) |
| ( | ( | ( | ( | ( | ( | ( | ( | ( | ( |
| ) | ) | ) | ) | ) | ) | ) | ) | ) | ) |