

August 2, 1983

-2-

To insure that your customer maintains confidence in his rifle, we are replacing the trigger assembly with the new style assembly that is found on our current model which does not have the bolt lock feature. This trigger design will allow the bolt to be opened with the safety switch in the "on safe" position.

We apologize for the delay in this matter and will expedite replacement of the trigger assembly and return shipment of the rifle to you.

Sincerely,

J.A. Stekl, Supervisor
Product Service

JAS:tpg