

BARBER - Kinzer PPS GAL RE0001011 RECEIVING AND ESTIMATING REPORT

ORDER
R93-10614

INITIAL	CUSTOMER ORDER NO.				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
4/23/93	04/26/93	DC 9-86	B6814615		700 30-06 BDL
ACCESSORIES W/STUDS					

FROM:	SHIP TO:
<i>Chapel Sports</i> CHAPEL SPORTS 116-20 ATLANTIC AVE RICHMOND HILL NY 11419	CHAPEL SPORTS 116-20 ATLANTIC AVE RICHMOND HILL NY 11419

ACCOUNT NUMBER		ACCOUNT NUMBER N/C	CUST NO: 004292 C.B.D	PROM. DATE	ESTIMATED	VIA
			WRITE ☐		5/25/93	UPS
UN CONDITION	<i>Customer bringing long gun</i>					REPAIR CHARGE
☐ NEW						EXCISE
☐ LIGHTLY WORN						TAX
☐ WORN						INSURANCE
☐ VERY WORN						UPS
☐ UNREPAIRABLE						PARCEL POST
☐ MARRED						TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	
BOLT ASSY.		B3			F2	
BARREL ASSY.		B4			F3	
REC. ASSY.		B5			F4	
WOOD		C1			F5	
METAL		C2				

MAIN FAULT: *Could not duplicate concern. However, upon receipt of bolt trigger assembly and trigger component working properly. Examination revealed heavy, sticky, gummy substance covering action, trigger assembly and bolt stop release.*

ARTS	COMMENTS				
<i>Upper Rec - 6 1/4 lbs</i> <i>Gun Bolt - .013</i>	<i>Replace complete trigger assembly and clean action at 1/2 normal adjustment test, is quiet and good with.</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>Roe</i>		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92