October 14, 1989

Dear Sir,

I am returning to you my Remington Model Seven 308 Cal. riple, Serial No. 7646466 which I recently purchased.

The problem I have is that the riple will accidently go off when I push off the safety.

This will happen about two out of tentimes.

Recently this happened at a local riple tange and fortunately no one was hurt. The results could have been a disaster.

The malpunction had not occured for maybe the first twenty five (25) shots I fired, but now there are times when the riple wont even cock, and like I mentioned before there are times it will go off when pushing the safety to the fire position.

I called the factory to verify if the serial number was of the riples that were called back for safety reasons, they assured me it was not.

I have purchased BELL & CARLSON Riberglass stock for this riple and the problem seems to be more pronounced when it is in use.