

October 18, 1991

Remington Arms Co. Inc.
14 Hoefler Ave.
Ilion N.Y. 13357

Dear Jack:

I am shipping this rifle back to Remington on the advice of Mr. Dorn of Dorn's Outdoor's & Gun Repair in Macon, Georgia. He explained to me that the trigger mechanism is a factory defect, and has been replaced twice if I understood him correctly.

The problem I have, is when you chambered a round in the gun it would fire. Then if you got one chambered when you pushed the saftey to the OFF position the gun would go OFF again. My son and I own several Remington firearms and would like to have this one corrected or replaced.

If you have any questions or I can be of any assistance to you please call me at my place of business (collect will be fine) 912-929-5679. If you can't reach me leave your number and message and I will be glad to return your call.

Looking forward to using Remington Firearms in the future and certainly appreciate your cooperation in handling this problem.

Sincerely,


Richard Cleghorn



Richard Cleghorn /
OWNER

Cleghorn Cabinet's

705 ELBERTA ROAD
P.O. BOX 1673
WARNER ROBINS, GA 31099

HM 912-953-5600
Bus: 912-929-5679