

BARBER - Kinzer PPS GAL RE0001163

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R # : 025024
 OUTSIDE WORK: SCOPE MOUNTED, ALL DATE: 12-5-72
TRIGGER ADJUSTMENTS CHANGED. FROM: COMMUNITY HDW. CO.
 FIRED AMMO TYPE: - THOMASVILLE, N.C.
 & CONDITION: _____ GUN # : 6338169
 PROOF: R.E.P. ASSEMBLER IS _____ INSPECTION: 9 TEST: 87 CODE: KT-5/70
 HEADING: O.K. GA./CAL.: 25-06
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: 15 ROUNDS - NO PIERCING APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN, SEAR DAMAGED. PRIMER
PIERCING IS INDICATED.

COMPLAINT: "BOLT FIRES WHEN YOU PUSH IT DOWN"

INCIDENT: FOLLOW DOWN.

COMMENTS: WITH THE TRIGGER CONNECTOR BROKEN THERE IS NO WAY
THE ACTION CAN BE COCKED. THE BREAK DOWN EVIDENTLY
STARTED WITH PRIMER PIERCING.