

P.I. YES GUN EXAMINATION REPORT NUMBER: 114 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 15597
 OUTSIDE WORK: SIGHTS REMOVED DATE: 5-17-79
SCOPE BASE ADDED FROM: DAVE'S GUN SHOP
SALEM RD BRIDGEVILLE
 FIRED AMMO TYPE: NOT KNOWN GUN #: A6537717
 & CONDITION: _____ CODE: X-0-12-77
 PROOF: REF U INSP.: U TEST: 112 GA./CAL.: M-121904
 HEADING: _____ OK CHECKED BY: GHA 6/2/79
 BREECH OPENING: _____ OK APPROVED: _____
 RECOIL SHOULDERS: _____ OK APPROVED: R.F.B. 6-22-79
 CHAMBER: _____ OK APPROVED: X-0-12-77
 TEST: _____ APPROVED: 2094 6-22-79
 COMPONENT CONDITION: (Damaged, Broken, Old Style)

BBL. MAR. AT MUZZEL TOP
FLOOR PLATE BRIGHT

COMPLAINT: FIRED WHEN SAFE WAS MOVED TO OFF POS.

INCIDENT: BLEW HOLE THRU PASSENGER DOOR

COMMENTS: Unable to duplicate customer complaint. Trigger
pull below spec. - has been adjusted
outside Remington - trigger stop screw sealed rot of Remington
type. Safety has also been removed as indicated
but safety detent screw not in proper position.
- Gun passed tick test
- Serial lift .007
- Time 2.11 13.14