

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
VITAL		CUSTOMER ORDER NO.				R 93-13150	
JJM							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
06/04/93	06/07/93	DQ 9-78	A6657321		700 243 ADL		
ACCESSORIES		W/STDS		W/STDS		SCOPE BASE	
						L/REAR SIGHT	
FROM:				SHIP TO:			
DAVID C ROSE GUNSHOP				DAVID C ROSE GUNSHOP			
12521 W HWY 162				12521 W HWY 162			
FARMINGTON				FARMINGTON			
AR 72730				AR 72730			
CUST NO: 000184 ILIONL							
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		FROM DATE		ESTIMATED	
				6-30-93		UPS	
SUN CONDITION		WRITE ☐		REPAIR CHARGE		25.00	
☐ NEW				EXCISE			
☐ LIGHTLY WORN				TAX			
☐ WORN				INSURANCE			
☐ VERY WORN				UPS			
☐ UNREPAIRABLE				PARCEL POST			
☐ MARRED				TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4			E3	F3	
REC. ASSY.		B5			E4	F4	
WOOD			C1	D2	E5	F5	
METAL			C2	D3			
MAIN FAULT							
Upon receipt could not start function. Trigger Safety Lever frozen. Had to trigger manually from an unknown heavy gunning. Reassembly Bolt stop release also frozen up. Rifle made good working. May 1998							
PARTS				COMMENTS			
				Explosive Corruptive Trigger Assembly at 1/2 normal replacement cost. It gives up good used, & clean action			
				Go ahead			
REPAIRMAN		PROOF		CLEAN		TEST	
KBS				✓		✓	
GALLERY TESTER		DATE		DATE		DATE	