


Since we found the trigger assembly to be outside our specifications, we can either properly re-adjust the present assembly or, if it will restore your confidence in the rifle, we will install a new trigger assembly with the new-style safety that allows opening the bolt with the safety in the "on-safe" position, at no-charge as a gesture of good-will. We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS:tp

Remington Arms Company, Inc.