BARBER - 5.22.06r0001469

RE FUNCTION TEST.txt

From: Reesor, Phillip K.

Sent: Tuesday, September 12, 2000 1:05 PM

To: Danner, Dale; Franz, Scott Subject: RE: FUNCTION TEST

Latest is that the mag box in two rifles has come apart one time.

From: Reesor, Phillip K.

Sent: Tuesday, September 12, 2000 11:51 AM

To: Danner, Dale; Franz, Scott

Subject: FUNCTION TEST

First reports from function testing are that the feeding seems ok, however the bolt operation is very stiff, especially the downward move ment

of the bolt to lockup the action. Not smooth at all.

PKR

Page 1