

To whom it may concern:

Enclosed you will find A Remington
XP-10.0 .35 REM serial number B7520484.
The gun was purchased 3/17/88 from
Shooters Supply Holcomb, NY.

The gun had been fired approximately
35 times before it blew out on 4/30/88.
Of the 35 rounds fired threw the gun
the last 10 rounds were handloads. These
handloads had been carefully researched and
fired in 3 different Thompson Contenders
previously with no adverse results. The
load consisted of 43 grains of H322 with
A 180 grain Speer flat point bullet and large
rifle magnum primers. The brass used was
once fired Remington brass which had each been
checked for length. The individual charges had