

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO. 1597		COMMENTS	
DATE RECEIVED 04/26/88	DATE OPENED 05/04/88	DATE CODE DQ 9-78	SERIAL NUMBER A6645123
MODEL AND GRADE 700 30-06 BDL		ORDER 88-12826	
ACCESSORIES W/STUDS			
FROM: LESLIE EDELMAN OF NEW YORK 75 SHERWOOD AVE (PRO) FARMINGDALE, NY 11735		SHIP TO: LESLIE EDELMAN OF NEW YORK 75 SHERWOOD AVE (PRO) FARMINGDALE, NY 11735	
ACCOUNT NUMBER	FROM DATE	ESTIMATED	VIA UPS
REPAIR CHARGE	TAX ST	INSURANCE	UPS
TAX CITY	TAX CITY	PARCEL POST	TOTAL
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE			
CUSTOMER'S COMPLAINT <i>Gun fires when Bolt closes</i>			
MAIN FAULT <i>Unable to duplicate alleged complaint - action operates properly - trigger pull 4 1/2 lb, sear lift .0095"</i>			
<i>Trigger adjusted out of factory as evidenced by</i>			
<i>excess spring on overtravel weight of pull sensor</i>			
DEMERIT CODE			
<i>Check trigger adjustments and re-set sensor, test and return rifle to sender.</i>			
<i>5/20/88</i>			
<i>jes.</i>			
FOR COMPUTER REF. ONLY		PROOF	
		(CLEAN) (TEST) (TARGET)	
		REPAIRMAN <i>R.B.S.</i>	