

BARBER - Kinzer PPS GAL RE0001635

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NO (E)NACT 04/04/91
 ENTER REPAIR NUMBER -----> 9024787 13 11 59
 120272 MODEL: 660
 FROM: (CUST NUM: 030234) ANDERSON GA/CAL: 06.5 MM
 ANDERSON HAROLD TYPE: LS
 PO BOX 171 ACCESSORIES: W/STUDS
 100 ELDER RD
 MANCELONA MI 49659
 SHIPPED TO:
 ANDERSON HAROLD
 PO BOX 171
 100 ELDER RD
 MANCELONA MI 49659
 COMMENTS: ATTN JIM STEKL
 DATE CODES: OR 7-68
 OTHER ACCESSORIES:

DATES:		TO	FROM	
RECEIVED	09 14 90	GALLERY	09 28 90	10 15 90
OPENED	09 26 90	PROD SERV	00 00 00	09 27 90
ESTIMATED	10 01 90	TAG GUNS	00 00	
PROMISED	00 00 00	REJECTED	00 00	
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	
SHIPPED	10 16 90			
BILL TYPE N/C		PF1 = VIEW DETAIL		

REPAIR NUMBER: 9024787 NO CHARGE EST/LETTER LSTD 04/04/91
 CUSTOMER NAME: ANDERSON HAROLD 13 12 46

REQUEST: SEE ATTACHED LETTER.
 MAIN FAULT: TRIGGER ASSEMBLY CONTAMINATED WITH GUMMY RESIDUE; INTERNAL
 PARTS NOT MOVING FREELY - SEAR SAFETY CAM IS STUCK TO
 ASSEMBLY SIDE PLATES.
 PARTS: \$ 0.00 1 91469 TRIGGER HOUSING ASSEM
 LABOR: \$ 0.00 THIS GUN SUBJECT TO M/600 RECALL - STILL HAS ORIGINAL
 \$ 0.00 TRIGGER ASSEMBLY.
 \$ 0.00 INSTALL NEW TRIGGER ASSEMBLY AT N/C UNDER RECALL.
 \$ 0.00 TEST.

TOTAL VALUE:\$ 0.00 CLEAR = RETURN
 NO MORE DATA AVAILABLE FOR THIS REPAIR