

RECEIVING AND ESTIMATING REPORT

INITIALS		CUSTOMER POLICE NO.		COMMENTS	
JUM				ATTN: J. STEEL	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MOORE AND GRADE	ORDER
08/18/78	08/19/78	0047-7811	A4482657	701 220	BDL
HUNT/STUDS		SCOPE BASE		L/SIGHTS	
FROM			SHIP TO:		
FARRINGTON, ROBERT 3626 LAKE PONTCHORTRAIN ARLINGTON TX 76016			FARRINGTON, ROBERT 3626 LAKE PONTCHORTRAIN ARLINGTON TX 76016		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROML DATE	ESTIMATED	MAILED
					UPS
REPAIR CHARGE					
TAX					
INSURANCE					
UPS					
PARCEL POST					
TOTAL					
GUN CONDITION:					
☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED					
CUSTOMER'S REQUEST					
<i>"The gun discharged when the safety was released"</i>					
MAIN FAULT					
<i>Could not duplicate complaint. However, trigger pull felt like main spring at 2 3/4 # and also tried out of spec also (excessive) 2 1/2 - 3 1/2 #. Bolt stop has accumulation of dirt oil and sludge sometimes.</i>					
PARTS					
<i>Offer to either re-adjust present trigger assembly back into specification or, if it will better restore confidence in up, we can install a new trigger assembly, at no charge, as a gesture of good-will.</i>					
<i>Either option is subject to handling plus return shipping charges/25/00 JLS.</i>					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88