BARBER - Kinzer PPS GAL RE0001702

October 27, 1986 DASUMER SEDINOE CRIVED - 7 1988 K. D. G.

Consumer Protection Remington Arms Company, Inc. Wilmington, Deleware, 19898

To Whom It May Concern:

On December 22, 1981, I purchased a used Remington Mohawk 600-Cal. 308-ser. #A6390843.

October 26, 1986—upon returning from hunting I set the gun on the floor boards of my truck. At that time I took the safety off to unload the gun and it discharged. The bullet went through the firewall and into the intake manifold, cutting several wires. The damage will run the hundreds of dollars. I do not know if this has happened before with this model rifle, but I thought I should notify you. Please advise me on how to prevent this from recurring.

Fortunately no one was injured, and we were able to jury rig the truck in order to drive it home.

Sincerely, harles E. Fennestt

Charles E. Fenner, III 541 Cushing Ct. Brookings, Oregon 97415 503-469-4418