

ESTIMATE REPORT

RECEIVED R 20277 7

Five Points Sport Shop, Inc.

P. O. Box 132

ROUTE 512 — SANGOR, PENNSYLVANIA 18013

215-688-4143

Remington Arms:

*GUN FIRES when safety mechanism
is disengaged, before trigger function
is employed. This happened when
RIFLE was still in manufacturers condition,
CAUSING A discharge in the buyers home.
PLEASE REPAIR. IF ANY CHANGE notify:*

*John L. Zeruth, mgr.
Five Points Sport Shop*

John L. Zeruth mgr.