## **BARBER - Kinzer PPS GAL RE0001767**

We do want to be as helpful as possible to our customer and, therefore, as a gesture of good-will, we will properly re-adjust and re-test the trigger assembly at no charge before returning the rifle to you. Please allow sufficient time for this service to be performed.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

J.A. Stekl, Specialist

Product Service

JAS: tpp

Remington Arms Company, Inc.