

BARBER - Kinzer PPS GAL RE0001819 AND ESTIMATING REPORT

FROM DATE _____

ORDER R 13072

DATE RECEIVED 5-24-84

ESTIMATED 6-4-84

JUN 5 1984

DATE OPENED 5-24-84

VA UPS

MODEL AND GRADE 200304-7MM Rem Mag.

SERIAL NO A1476974

updated w/repair base

DATE CODE D9 2-22

FROM

Thomas E. Francis
510 3rd Ave
Washington, Ky 40383

REPAIR CHARGE 2487.80.55

INS _____

UPS _____

PARCEL POST _____

TOTAL \$ _____

GUN CONDITION (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT the rifle fired while extracting a shell

STAFF FAULT Initial Trigger tint. steel when fired

PARTS

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

FOR COMPUTER REPAIR ONLY

51111