

Cust Comp.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: FAIR R #: 000014
OUTSIDE WORK: SCOPE MOUNTED, BUTT PAD DATE: 1-4-73
FITTED. SEALS REMOVED - TRIGGER FROM: W.K. FRAYSUR
FIRED AMMO TYPE: - HOUSTON, TEXAS
& CONDITION: _____ GUN #: 69329
PROOF: R.E.P. INSP.: 5 TEST: 13 CODE: PK-5/63
HEADING: ? GR./CAL.: 270
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: - APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EXCESSIVE LUBRICANT, TRIGGER BIND ON TRIGGER
GUARD POSSIBLE.

COMPLAINT: "WILL FIRE ACCIDENTALLY ON PUSHING OFF THE
SAFETY"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED,
IT PROBABLY IS ASSOCIATED WITH TRIGGER BIND
AND TYPE OF LUBRICATION USED.