

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27538

CUSTOMER ORDER NO.					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
1/07/93	12/15/93	BN 1-66	193953		700 222 ADL
SSORIES W/STUDS SCOPE BASE					

SHIP TO:	
BILLY FRED'S SALES CO PO BOX 7646 2465 I-40 WEST AMARILLO TX 79109	BILLY FRED'S SALES CO PO BOX 7646 2465 I-40 WEST AMARILLO TX 79109

QUANTITY	ACCOUNT NUMBER N/C	CUST NO: 006802 WFLM	PROM. DATE	ESTIMATED	VIA
				1-14-94	UPS
CONDITION			REPAIR CHARGE		
NEW			25.00		
LIGHTLY WORN			EXCISE		
WORN			TAX		
VERY WORN			INSURANCE		
UNREPAIRABLE			UPS		
DAMAGED			PARCEL POST		
			TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
TRIGGER GROUP		B2			E1	F1
T ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5			E4	F4
JD					E5	F5
AL						
FAULT: Upon receipt rifle in action. Trigger was not reset. Information provided that the trigger and trigger assembly are covered with heavy sticky substance. One person only trigger pull manual labor minimum 30 minutes. Substant on trigger adjustment and stop screw, not require adjustment. Adjustment made without failure. Rifle with good accuracy. Replace trigger assembly & other action at 1/2 normal replacement cost, as given & good will						
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN
C C						
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/92