

79735 8-3-19-93

Fort Stockton Texas

Remington Model 700 Cal. 30-06
BDL SPRG.
Serial # 6421105

This Rifle has a Problem With
the Trigger & safety; Especially
after it sits up for a while,
When you work the Bolt you
can't work the safety, and
some times it will fire.
The Trigger is real hard.

I Would appreciate it if you could
Haul This Rifle Back to me BY or
Before the 25th of Sept. Because I have
a Handicapped ~~Elk~~ Elk Permit to
Hunt. Sept. 29 through Oct. 3.

Thanks Donald F. Garrison
600 W. 5th St.
Fort Stockton Tex.

Shipped Everything Except 79735
the Stock.

RD6625 REV. 1/74