

JOHN L. GEISER
ATTORNEY
511 EAST HAMILTON AVENUE
STATE COLLEGE, PA 16801
814-234-0260

January 3, 1991

Remington Arms Company, Inc.
939 Barnum Avenue
P.O. Box 1939
Bridgeport, CT 06601

Gentlemen:


Until recently I was the proud owner of a Remington Model 700LH, Serial No. A6828535, .270 Winchester. I am no longer proud.

During last year's buck season (December 1989) I was approached by a herd of deer. I was in a standing position, behind a tree, and began releasing the safety with my thumb and forefinger to avoid the "click." The rifle discharged. I unloaded the remaining shells, left the woods and subsequently took the rifle to one of your dealers for inspection and repair. I was later contacted and advised that the situation had been corrected. I picked it up, paid for the repairs and put the rifle away.

On opening day of the recent buck season (November 26, 1990) I spent an uneventful and fruitless day in the woods. When our group returned to the trucks at the end of the day, we began to unload. As I released the safety (mandatory in order to unload the chamber), the rifle discharged. By the grace of whatever higher authority looks over us - and our group's mutually enforced practice of never having a weapon pointed at another - a disaster was averted with only shattered nerves and ringing ears remaining in testimony of the event.

This rifle has been fired less than fifty times. It will never again be fired - by me. I would appreciate the opportunity to discuss a replacement with your representative.

Very truly yours,


John L. Geiser

JLG/lad