

ORDER
R 92-02928

FROM:	SHIP TO:
GEM SPORTS SUPPLY CO. 625 BURNETT AVE. SYRACUSE NY 13203	GEM SPORTS SUPPLY CO. 625 BURNETT AVE. SYRACUSE NY 13203

CUST NO:004064 ILION L

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL	100
--	--

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

As received, it would not work. Disassembly of pipe revealed that the trigger assembly has been improperly adjusted outside factory (as evidenced by red solvent on rear engagement screw) - insufficient rear engagement. Trigger pull 2# - well below our maximum spec.

PARTS

COMMENTS

COMMENTS Send quotation for replacement
to be assembled at the normal cost as
given of good-will.

If Note — warn customer about advertising
triggers outside factory

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

DATE

DATE _____

DATE

DATE _____

DATE

OFFICE COPY

RD6925 REV. 8/91

BARBER - Kinzer PPS GAL RE0001965

PPS 01960