

BARBER - Kinzer PPS GAL RE0001970

REC

IG AND ESTIMATING REPORT

ORDER

R 94-17095

INITIAL

CUSTOMER ORDER NO.

JJM

ATTN Jack Kart

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/27/94

05/31/94

RM 11-92

C6748955

700 270

CS

ACCESSORIES

FROM:

GIBBS GUN SHOP
RR 2 BOX 234
METTER

GA 30439

SHIP TO:

GIBBS GUN SHOP
RR 2 BOX 234
METTER

GA
30439

CUST NO: 097964 C-D.DL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE

☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☒ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

Bolt makes squeaking noise

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

Accidentally dry fired twice during operation of bolt

BARREL ASSY.

B4

D1

E2

F3

REC. ASSY.

B5

D2

E4

F1

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

May 11-92 Unable to make gun malfunction as described or any other way as received. Change trigger assy. due to variation in trigger pull and to restore customer confidence in the rifle. Change firing pin assy. to eliminate squeak.

PARTS

COMMENTS

Trigger pull measured 4 1/2 to 5 3/4 lbs as rec'd spec 4 1/2 to 5 1/2

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

FD6925 REV. 1/94

BARBER - Kinzer PPS GAL RE0001970

PPS 01965