

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 29327
OUTSIDE WORK: EXTRACTOR RIVET GROUND OFF. DATE: 12-15-70
TRIGGER ADJUSTED - ENGAGEMENT SCREEN FROM: HARDER SGT. GOS.
APPEARS UNTOUCHED. WILLIAMSPOOT, PA.
FIRED AMMO TYPE: - & CONDITION: _____ GUN #: 6264372
PROOF: R.E.P.-E ASSEMBLER IS _____ INSP.: 7 TEST: 55 CODE: WIS-8/69
READING: O.K. CR./CAL.: 7.62 REM.
BREECH OPENING: - CHECKED BY: C. PCOSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DEFECTIVE OR BROKEN COMPONENTS.

COMPLAINT: "FIRED UPON CLOSING"INCIDENT: FOLLOWED DOWN

COMMENTS: SEAR-CONNECTOR ENGAGEMENT .003, MINIMUM IS .015,
THIS LETS THE SEAR SLIP OFF THE CONNECTOR UNDER
PRESSURE AND FOLLOW DOWN RESULTS.