

Cash Comp

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600
GENERAL CONDITION: GOOD R #: 020681
OUTSIDE WORK: SCOPE MOUNTED DATE: 10-11-72
FROM: JAMES A. HASTER
FIRED AMMO TYPE: - LITTLE FALLS, N.Y.
& CONDITION: _____ GUN #: 61732
PROOF: R.E.P. ASSEMBLER 5 INSP.: 49 TEST: 54 CODE: KP = 6/67
HEADING: O.K. GA./CAL.: 308 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR SPRING INCORRECTLY POSITIONED. TRIGGER
RUSTED AND IMMOVABLE. EXCESSIVE LUBRICANT ON
SEAR- SAFETY CAM.

COMPLAINT: FIRES WHEN CLOSING, RELEASING SAFETY

INCIDENT: FOLLOW DOWN

COMMENTS: THE SEAR SPRING COULD NOT PUSH THE SEAR
UP INTO POSITION TO HOLD THE FIRING PIN IN COCKED
POSITION. THE TRIGGER RUSTED IN FIRED POSITION
COULD NOT RETRACT TO HOLD THE SEAR IN CONTACT
WITH THE FIRING PIN.