

BARBER - Kinzer PPS GAL RE0002334

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 026064
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-5-72
 FROM: HERTER'S INC.
 FIRED AMMO TYPE: - OLYMPIA, WASH.
 & CONDITION: _____ GUN #: 6524373
 PROOF: R.E.P.-B INSP.: 74 TEST: 97 CODE: CW = 4/72
 HEADING: O.K. GA./CAL.: 3006
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025(MIN IS
.020) CONNECTOR = 1.088 MODEL DRAWING = 1.080, TRIGGER
MEASURES 1.074, MODEL DRAWING = 1.076

COMPLAINT: "FIRES WHEN SAFETY IS PUSHED OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED, HOWEVER, THE .007 OVER MAX. CLEARANCE
BETWEEN THE TRIGGER AND CONNECTOR WILL ALLOW
THE CONNECTOR TO INTERFERE WITH THE SEAR AND
FAILING TO RETRACT INTO COCKED POSITION, CAUSE
A FOLLOW-DOWN.