

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-10227

INITIAL FJB	CUSTOMER ORDER NO.		W/ SOFT CASE			
DATE RECEIVED 03/18/94	DATE OPENED 03/21/94	DATE CODE PZ 6-75	SERIAL NUMBER 6881186	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS		

FROM:

SHIP TO:

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINE

IN 46163

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINE

IN
46163

CUST NO: 014391 C-D-DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 5-6	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		F1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

When we received the gun we would not insert bolt assembly. The bolt stop
 where was covered with a heavy, thick, and gummy substance. The receiver
 would not function as designed. We could not duplicate the unintentional
 discharge concern. They said we missed 4 1/2 lbs. Gun shot: OK

The action is also covered with this gummy substance. Rifle needs a good
 cleaning. What then normal function required at time to make safety.

Repaired trigger assembly
 & other action at 1/2 normal
 movement but no further of good was

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1