

Rt 1 Box 681
Floyd, VT 24091
Nov 3, 1992

Remington-Union Co
14 Hoosier Ave
Elion, NY 13357

Ref: Model 700, Ser# 63337-29, Bolt # 3729

Dear Sirs:

I spoke with one of your reps while attending the World Steel Shoot at Annapolis recently and discussed the problem of my 700 firing as the safety is placed in firing position without any contact with the trigger.

I would appreciate return as soon as possible since hunting season has just begun.

Thank you,
B. Mal Honeycutt

B MAL HONEYCUTT

703 745 3330 ex

703 854 5857