

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS WOG 1 OF 2 W/LEUFOLD 3X9 SCOPE & CAPS <i>in separate line</i> STOCK NOT OUR MFG	
DATE RECEIVED 11/22/91	DATE OPENED 01/29/91	DATE CODE RT 11-70	SERIAL NUMBER 6382936	MODEL AND GRADE 700 270	ORDER R 91-0299
ACCESSORIES W/STUDS <i>4 Bolt</i>		SCOPE MNTS	SCOPE BASE	HARD CASE	
FROM: HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429			SHIP TO: HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED
				VIA	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"My 270 has fired several times throughout the year by simply pulling the gun off safety"

Tugger has been improperly adjusted outside the factory as evidenced by non-Remington sealant on the adjusting screws. 1) excessive over travel 2) insufficient retraction spring force - trigger is not retracting consistently - trigger pull varies from 2 1/2 pounds to 4 1/2 pounds. Seen left O.K. at 011"

Re-adjust present trigger assembly to specification, if possible, if not, offer new trigger assembly at 1/2 refund cost as gesture of good-will.

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90