

CUSTOMER ORDER NO

W/1 SPENT CASE

DATE RECEIVED 12/02/85	DATE OPENED 12/09/85	DATE CODE BB 1-81	SERIAL NO. B 6282261	MODEL AND GRADE 700 30-06 BDL	ORDER R 85-2456
---------------------------	-------------------------	----------------------	-------------------------	----------------------------------	--------------------

SWIVEL STUD

FROM:

SHANNON HUSTON
704 GALAXY
HARRISONVILLE, MO.

SHIP TO:

64701

REPAIR CHARGE	INSURANCE	UPS	PARCEL POST	FROM DATE	ESTIMATED	VIA UFS	TOTAL \$
---------------	-----------	-----	-------------	-----------	-----------	------------	-------------

GUN CONDITION:

☐ NEW☒ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ QUOTE

CUSTOMER'S COMPLAINT

"Fixed upon releasing safety - happened twice"

MAIN FAULT

Could not duplicate alleged malfunction - however bottoming receiver
and trigger assembly dripping wet with oil.

DEFECT CODE

PARTS

Clear oil off rifle and install new
style trigger assembly (no bolt-
at no-charge).

Please expedite!

1/3/86

Jas

FOR COMPUTER REF. ONLY

PROOF

(CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY