

8-8-92

Arms Service Division  
Remington Arms Company, Inc  
Ilion, NY 13357

Dear Sir:

Enclosed please find my Remington model 700 (serial # 6478324) .270 caliber bolt action. I am having a problem with the safety - when I release the safety from safe to fire the firing pin trips before I pull the trigger. ~~It also fires~~ The firing pin also trips sometimes when locking the bolt into place. The gun is malfunctioning in this manner intermittently (it only does this sometimes) and currently it seems to be working fine; however, as you can imagine if this occurs only once at the wrong time a serious accident could result. I have not had a shell in the chamber so far and have been lucky that an accident has not occurred. Please give me an estimate of the cost to repair (if any; my local sporting goods ~~store~~ dealer said you would not charge for this type of repair) before repairing. I can be reached in