

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS ATTN JIM STEKL	
CS	DATE RECEIVED 5/20/91	DATE OPENED 05/23/91	DATE CODE BU 1-71	SERIAL NUMBER 6492205	MODEL AND GRADE 700 270 ADL
ACCESSORIES	SCOPE BASE				ORDER 91-11206

L/REAR SIGHT

FROM:	SHIP TO:
JACKALOPE GUN SHOP 1048 SOUTH 5TH ST. DOUGLAS USA	JACKALOPE GUN SHOP 1048 SOUTH 5TH ST. DOUGLAS USA
WY 82633	WY 82633

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
CUSTOMER'S REQUEST					

"... This rifle fires when safety is released or the bolt is closed."

IN FAULT	No fault found - cannot duplicate above complaints. Trigger pull 5 pounds, rear - lift .009". However, removal of action from stock revealed excessive dirt and oil on bottom of action and on trigger assembly. Rifle has not been properly maintained.
----------	--

RTS	Offer to return rifle with present trigger assembly, after cleaning, or offer to replace trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90