

Remington Arms:-

3/30/94

I AM SENDING you my MODEL 700, 3006 RIFLE. THIS RIFLE HAS NOT BEEN FIRED IN SEVERAL YEARS DUE TO A SAFETY PROBLEM. THE LAST TIME IT WAS USED IT DISCHARGED WHEN THE BOLT WAS PUSHED DOWN. THAT MORNING THE RIFLE WOULD NOT GO ON SAFETY. I PULLED THE BOLT OUT AND THE SAFETY THEN WORKED, BUT WHEN I PUSHED THE BOLT IN AND DOWN THE RIFLE WENT OFF. THAT DAY IT ALSO WAS DISCHARGING BY JUST PUSHING THE BOLT IN. MY 15 YEAR OLD SON WAS WITH ME WHEN THIS HAPPENED, SOMEONE COULD HAVE BEEN KILLED.

ON SUNDAY MARCH 20TH ON CHANNEL 11 IN HOUSTON THE SHOW 60 MINS RAN A PROGRAM ABOUT THE MODEL 700, ABOUT HOW DANGEROUS THIS RIFLE IS. I HAVE A SERIAL REMINGTON FIRE ARMS AND THINK YOU SHOULD REPAIR THIS AT NO COST.

THANKS

Don Jackson

2206 Peyton Place

DOER PARK, TX 77536

HM 713-479-8398 WK 713-246-7085