

RECEIVING AND ESTIMATING REPORT

R93-09752

CUSTOMER ORDER NO. L46035		DATE OPENED 04/13/93		DATE CODE	SERIAL NUMBER A6663447	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL/LH
RECEIVED 02/93	DATE OPENED 04/13/93	DATE CODE	SERIAL NUMBER A6663447	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL/LH		
W/STUDS		SCOPE BASE		L/SIGHTS			

SHIP TO:

JAY'S SPORTS
N 88 W 15263 MAIN ST
MENOMONEE FALLS

WI 53051

JAY'S SPORTS
N 88 W 15263 MAIN ST
MENOMONEE FALLS WI
53051

CUST NO: 007266 IL10N

NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE
HTLY WORN					EXCISE 85.00
RN					TAX
Y WORN					INSURANCE
REPAIRABLE					UPS
RED					PARCEL POST
					TOTAL

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
ER GROUP		B2				F1
SSY.		B3			E2	F2
L ASSY.		B4		D1	E3	F3
SSY.		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

Upon receipt of rifle, ammunition revealed firing pin of trigger
has been badly bent down and removed. The end of the trigger
that the inside of the trigger found bent. All parts removed.
Inspected for bent trigger. The firing pin was bent, the firing pin was bent,
this will affect the firing pin. (See picture of ammunition, note attached)

COMMENTS

Repaired trigger assembly, complete set
for normal replacement set.

Go ahead - OK per JPL 4/15/93

REPAIRMAN WBA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/92