

RECEIVED

JAN 31 1989

R.B. SPERLING

RECEIVED

JAN 25 1989

CONSUMER SERVICE
1-16-89

Dear Sir - To whom it may concern
I am the owner of a Remington
Model 700 ADL Bolt Action 308
Caliber Rifle that I purchased
on date of 10-8-1984. Serial number
is B6483050.

During Deer season in November
of 1984 it misfired once when
I closed the bolt loading another
shell in the barrel. It fired
just as I got the bolt closed and
before I had the chance to
push the safety lever into
safety position. I know you
published a recall article in
the paper about a year ago
on some that were defective
but I was informed that they
were later models than mine.
I'm very concerned again
now after reading a article