

24704

## REMINGTON GUN AND/OR TRAP REPAIR INVOICE

REMINGTON ARMS CO., INC.  
LION, N.Y. 13357

## Remington Recommended Repair Facility

Name Kendall's Gunsmithing, 501 1st St  
 Street 927 JEFFERSON AVE  
 City WASH State PA Zip 15301

Customer's Name Kenneth Hall  
 Street 239 Rock Creek Hill St  
 City Coudersville State PA Zip 15431

| Date Firearm or Trap Received          |                                | Date Returned to Customer |                          | Returned to Factory              |     |
|----------------------------------------|--------------------------------|---------------------------|--------------------------|----------------------------------|-----|
|                                        |                                |                           |                          | Date                             | Via |
| 11-16-90                               |                                | 11-16-90                  |                          |                                  |     |
| Gun Model<br><u>706</u>                | Cal. or Gauge<br><u>7.62mm</u> | Grade<br><u>B&amp;A</u>   | Barrel Code<br><u>PH</u> | Serial Number<br><u>11541721</u> |     |
| Trap Model<br><input type="checkbox"/> | Counter #                      | Serial Number             |                          |                                  |     |
| Trap <input type="checkbox"/>          | Skeet <input type="checkbox"/> |                           |                          |                                  |     |

## Complete Description of Customer's Complaint

RIFLE FIRED WHEN SAFETY IS ROTATED TO FIRE POSITION

## Repairs Performed—Describe in detail

MINOR FAULT: TRIGGER DID NOT RETURN  
TO RESET POSITION AFTER BEING PULLED  
THERE IS VISIBLE EVIDENCE OF RUST ON TRIGGER  
MECH. WE FEEL THIS WAS THE PROBLEM WE ARE  
SENDING THE DEFECTIVE TRIGGER MECH TO THE  
ATTENTION OF MR. FRANK L. WHITE TO BE  
EXAMINED BY YOUR TECHNICIAN  
WE FIT A NEW TRIGGER MECH & YOUR FIRM WILL  
RECEIVE TRIGGER MECH. CHARGE

## Repair Charge Breakdown

|                 |                 |
|-----------------|-----------------|
| Parts           | \$ <u>42.48</u> |
| Labor           | <u>12.50</u>    |
| Test Ammunition |                 |
| Testing Targets |                 |
| Packing         |                 |
| Transportation  |                 |
| Total           | \$ <u>54.98</u> |

## GUNSMITH FILE COPY

Arms Service (2)  
 REMINGTON ARMS CO., INC.  
 LION, N.Y. 13357

Date: 11-16-90