

RECEIVING AND ESTIMATING REPORT

CUST NO: 047139 C.O.D		COMMENTS ATTN: ED JOY	
INITIAL PS	CUSTOMER ORDER NO.		
DATE RECEIVED 7/31/91	DATE OPENED 08/07/91	DATE CODE 06 7-86	SERIAL NUMBER B6803725
ACCESSORIES W/STUDS		MODEL AND GRADE 700 270 WIN ADL	
			ORDER R 91-15225

FROM:

KNAUS, KIRK L
5526 W 4TH AVE
LAKEWOOD
USA

CO 80226

SHIP TO:

KNAUS, KIRK L
5526 W 4TH AVE
LAKEWOOD
USA

CO 80226

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

"... The problem is that the rifle on two separate occasions has fired when taking off the safety." ...

MAIN FAULT

Cannot duplicate complaint - no fault found. Trigger and safety assembly operate properly in every respect. Trigger pull 5 1/4 pounds; over-leaf .015"

ARTS

We can return rifle as-is or offer to replace trigger assembly at 1/2 normal charge, as a gesture of goodwill, if it will help restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90