

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORD R 93-133		
INITIAL JJM	CUSTOMER ORDER NO.							
DATE RECEIVED 06/08/93	DATE OPENED 06/09/93	DATE CODE AK 3-63	SERIAL NUMBER 59982	NEW SERIAL NUMBER	MODEL AND GRADE 700 222	ADL		
ACCESSORIES		SCOPE BASE						
FROM:				SHIP TO:				
LIVINGSTON, RICHARD M 4010 PEAKLAND PL LYNCHBURG VA 24503				LIVINGSTON, RICHARD M 4010 PEAKLAND PL LYNCHBURG 24503				
CUST NO: 079348 C.O.D.L.								
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 7-9-93	VIA	UPS		
GUN CONDITION			REPAIR CHARGE					
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			☒ EXCISE TAX INSURANCE UPS PARCEL POST TOTAL					
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	*INSPECT		
CYCLE	A	Was unable to get rifle off safe - manipulated for						
TRIGGER GROUP	+ safety then						E1 F1	
BOLT ASSY.	Can will fire when closing Bolt						E2 F2	
BARREL ASSY.	B4							E3 F3
REC. ASSY.	B5							E4 F4
WOOD							E5 F5	
METAL							C2	
MAIN FAULT Rifle mfg. 1963								
Upon receipt rifle would not function (would not fire). Upon								
disassembly that the trigger assembly has had the contact removed								
from the adjustment screw. Reinstalling it has been bypassed								
with.								
Replace complete trigger assembly								
Check firing pin assembly								
at 4x normal replacement								
cost go ahead								
REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET				
GALLERY TESTER	DATE	DATE	DATE	DATE				

OFFICE COPY

RD6