

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 03/07/91	DATE OPENED 03/11/91	DATE CODE RQ 11-78	SERIAL NUMBER A6693616	MODEL AND GRADE 700 270 CLASSIC		ORDER R 91-0684	
ACCESSORIES W/STUDS							
FROM: LOCK STOCK & BARREL 11 N MAIN ST CORNELIA GA 30531			SHIP TO: LOCK STOCK & BARREL 11 N MAIN ST CORNELIA GA 30531				
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 4-1	VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *hammer will fall when bolt is operated sometimes without trigger being pulled*

MAIN FAULT *Trigger assembly is contaminated with gunpowder residue - internal trigger parts are not moving freely - pin mechanism is stuck to side plate of trigger assembly - firing pin will sometimes follow down when bolt is closed. Rifle has not been properly maintained.*

PARTS *We can clean present trigger assembly, if possible, if we can offer to install a new trigger assembly at a nominal cost, if it better restore confidence in the rifle - gesture of customer good-will.*

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFF DE COPY

RD6925 REV. 7/90