
## **BARBER - Kinzer PPS GAL RE0003045**





Gibbes Goodwin

HINKE BERNERBER

. .

FFL 1-64-034-01-2M-33255

April 27, 1993

Remington Arms Company Arms Service Section 14 Hoefler Avenue Ilion, N.Y. 13357

Attn: Dennis Sanita

Re: R93-05444

Dear Dennis:

As we discussed by phone last week, Mr. Lester has asked me to authorize you to make whatever repair/replacement of the trigger system you deem appropriate, and return the model 700 BDL as soon as possible. He withdraws his request for help on the "Blazer transmission repair."

I believe the right thing to do is expedite the replacement of the trigger assembly and return the gun as quickly as possible.

Thanks again for your assistance.

Sincerely yours,

. Gabbes Goodwin

LGG/jg

Route 4, Box 2090 • County Home Road • Ellisville, Mississippi 39437 • (601) 477-GUNS