

RECEIVING AND ESTIMATING REPORT							
CUST NO 047032 B.O.D.		COMMENTS					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER		
08/23/91	08/27/91	DO19-77	A6502379	700 7MMHAG BDL	R 91-16857		
ACCESSORIES		W/STUDS		SCOPE BASE		L/SIGHTS	
FROM:				SHIP TO:			
LONG SHOT GUNSMITHING & SPORTS, THE 321 W SAGINAW HEMLOCK USA				LONG SHOT GUNSMITHING & SPORTS, THE 321 W SAGINAW HEMLOCK USA			
MI 48626				MI 48626			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	CLEAN/TEST	PROM DATE	ESTIMATED	VIA	
		☐			9/16/91	UPS	
PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL							
GUN CONDITION:							
☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED							
CUSTOMER'S REQUEST							
GUN FIRED WHILE UNLOADING							
MAIN FAULT							
Cannot duplicate complaint, rifle cannot be made to malfunction. however, trigger assembly has been properly adjusted out of factory as evidenced by trigger sealant on adjusting screws - 1) trigger pull below min spec. at 2-#2) excessive overtravel, 3) insufficient rear engagement. trigger is rusty also. See engagement lift .010"							
Note: stock broken at pistol grip. as received may not properly seated in action - may have caused cracked stock				Send again quotation for 1) stock and 2) new trigger assembly - to price as gesture of good-will.			
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN	
K22							
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/90