BARBER - Kinzer PPS GAL RE0003084

bcc: J. Hutton & B. Ericson

Remington.

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

September 19, 1989

Mr. Lionel Lopez 4325 Philippine Corpus Christi, TX 78417

Dear Mr. Lopez:

٣

Your letter of July 7, 1989, concerning the problem you experienced while hunting with your Model 700 30-06 caliber rifle, "just as I took the safety off, the gun misfired," has been referred to this office for response.

I apologize for this delay in responding to your letter, but with vacations and the resulting increase in work load, we are temporarily behind in correspondence.

We were sorry to learn of your having a problem with your rifle, and would like to examine it to try to determine the cause. To this end, we would appreciate your sending the rifle, along with a description of the use it has seen both before and after the incident, via U.P.S. transportation C.O.D. to:

> Remington Arms Co., Inc. Att: J.A. Stekl, Product Service 14 Hoefler Ave. Ilion, NY 13357

Please boldly mark the two (2) butt ends of the outside of the package "STEKL" to expedite handling.

We will contact you regarding our findings immediately upon completion of our examination.

. .

PPS 03079