


-2-

Since we found the trigger assembly to have been tampered with and outside our specifications, we can either re-adjust and re-seal the present assembly or, if it will better restore your confidence in the rifle, we will install a new trigger assembly at no-charge as a gesture of good-will (either option is subject to a \$10.00 handling plus the return shipping charge). We will await your decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Service

JAS:tp