

RECEIVING AND ESTIMATING REPORT

COMMENTS

XC! Field Supply

R

ORDER

94-11321

INITIAL FPS	CUSTOMER ORDER NO.		W/LEUPOLD 3 X 9 SCOPE		
DATE RECEIVED 03/29/94	DATE OPENED 03/30/94	DATE CODE	SERIAL NUMBER C4250204	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN MTN
ACCESSORIES HARD CASE		W/STUDS	SCOPE MNTS	SCOPE BASE	

KI 5-00 2ND TIME

FROM:

SHIP TO:

MARTIN, TODD
313 BAYWOOD RD
WEST CHESTER

PA 19382

MARTIN, TODD
313 BAYWOOD RD
WEST CHESTER

PA

19382

ACCOUNT NUMBER <i>053103</i>	ACCOUNT NUMBER N/C <i>059015</i>	CUST NO: 061673 C.O.D.	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION			REPAIR CHARGE <i>15.00</i>		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☒ MARRED			EXCISE		
<i>Because second time in for servicing</i>			TAX		
			INSURANCE		
			UPS <i>5.00</i>		
			PARCEL POST		
			TOTAL <i>23.00</i>		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT *mfg. 5/88 Unable to duplicate customers concern as rec'd. Trigger performed normally even when bolt was closed. Exchange trigger at spec price as a gesture of good will in order to restore customers confidence in the rifle.*

PARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	<i>Trigger pull measured 4 3/4 lbs as received. seal lift was .013</i>						
	<i>* Seal engagement was altered (.011) to .011</i>						
	<i>outside of factory witnessed by difference in Vsealant on firing screws and that of the engagement screw. Sealant on engagement screw was brownish vs clear on front as also contained debris & oil & was softer</i>						
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94