

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-13500

CUSTOMER ORDER NO.

JUN

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

06/22/92

06/22/92

XUU 12-49

99019

722

300SAV

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

OM

SHIP TO:

MASHBURN ARMS CO INC
1218 PENN AVE
OKLAHOMA CITY

OK 73107

MASHBURN ARMS CO INC
1218 PENN AVE
OKLAHOMA CITY

OK 73107

CUST NO: 005172 ILION

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

☐

CLEAN/TEST

PROM. DATE

ESTIMATED

7-8

VIA

UPS

CONDITION

NEW
LIGHTLY WORN
WORN
VERY WORN
UNREPAIRABLE
MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

IGGER GROUP

B2

LT ASSY

B3

E2

F1

RREL ASSY

B4

D1

E3

F2

C. ASSY

B5

D2

E4

F3

OD

C1

D3

E5

F4

TAL

C2

N FAULT

1) Safety has been removed from trigger assembly and improperly replaced. If system is not working properly and will not hold safety in position.
2) Rifle has been re-stocked with factory - insulating is not proper. Let safety lever move full distance into full safe position.

TS

COMMENTS

Send repair quote for stock insulating connection and new trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE