

RECEIVING AND ESTIMATING REPORT

MER ORDER NO.			COMMENTS		
			MOUNTAIN RIFLE		
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
2/26/88	03/03/88	WH 8-87	B6880822	700 270 MT	R 88-07363
SERIES		SCOPE MNTS		SCOPE BASE	
W/STUDS					

A: CARL MCKENZIE 429 LONGWOOD TR. MADISON MISS.		SHIP TO: CARL MCKENZIE 429 LONGWOOD TR. MADISON MISS.	
39110		39110	

NT NUMBER	FROM DATE	ESTIMATED	VIA
			UPS
CHARGE	TAX ST	INSURANCE	UPS
	TAX CITY		PARCEL POST
			TOTAL
			\$

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

MER'S COMPLAINT

re-attached description of incident → Fired when safety moved from FIRE to SAFE position - Damaged truck door

FAULT

1-19-88
EFS/RKP
Reassemble gun with original trigger which is perfect. DO NOT install this gun. ASAP to about customer RHP

DEMERIT CODE

ATTENTION: ABOVE SERIAL NUMBER IS ON
***** THE "TARP" MASTER FILE *****

① Try to duplicate incident from Fire to safe + then from safe to fire
② Do this without ammo +, if thought proper, with ammo in gallery.

③ Do any other non destructive test you think proper to try to duplicate incident.

④ Check connector condition
⑤ Give findings to KD Green x 407 ASAP.

COMPUTER REF. ONLY

PROOF (CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY