

RECEIVING AND ESTIMATING REPORT

INITIAL **FPS** CUSTOMER ORDER NO. **94-15230**

DATE RECEIVED **03/06/94** DATE OPENED **03/09/94** DATE CODE **PH 6-87** SERIAL NUMBER **B6837357** NEW SERIAL NUMBER MODEL AND GRADE **700 30-06 ADL**

ACCESSORIES **W/STUDS** L/REAR SIGHT

FROM: **MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION** SHIP TO: **MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION**

NY117-46 NY117-46

CUST NO: 097052 D.O.D

ACCOUNT NUMBER ACCOUNT NUMBER N/C WRITE ☐ FROM DATE ESTIMATED VIA **UPS**

GUN CONDITION

☐ NEW

☐ SLIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE **20.00**

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B5				
REC. ASSY.						
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Upon receipt bolt, spring and slide did not move in bolt head, firing pin threads. Could not disassemble because of firing pin in the bolt head. Firing pin did not move in barrel, slide, and trigger assembly. Gun engagement would have been a real life hazard from back of main frame.*

PARTS *Trigger pull - 5 1/2 lbs. Trigger spring - 1/2 lb.*

COMMENTS *When trigger is pulled, it does not move forward. When trigger is pulled, it does not move forward. When trigger is pulled, it does not move forward.*

REPAIRMAN **TAL** PROOF CLEAN TEST TARGET PATTERN

GALLERY TESTER DATE DATE DATE DATE DATE DATE

OFFICE COPY

RD6925 REV. 1/94