Dotober 15, 1976

Dear Sirs:

In October 1977 I purchased a Model 700 BBb in 7am Remington Magnum. It was purchased at Best Products Co., 6145 San Juan Ava., Citrus Heights, California. Enclosed is a photocopy of the receipt. The weapon is defective. Furthermore, the defect caused over 3600.30 in int yes to a vehicle inwhich I was a pescenter.

Basically, the defect is that the weapon discharges when putting the safty to the fire position. The defect first became apparent when the weapon dischared in said vehicle. The safty was in the safe position. I pushed the safty to the fire position, as necessary to open the bolt for unloading, and at that instant the weapon fired. The bullet hit the seatbelt buckle. Fragments ricocheted throughout the cab causing extensive damage to the seat, door panel, dashboard, windshield, side window, and steering wheel. Fragments also continued through the door.

It is my considered opinion that your company is responsible not only for repairing the weapon, but also for the damages to the truck. Enclosed is a copy of the damage estimate.

Those of us who witnessed the incident felt both angry about the damage and thankful there were no personal injuries. Further investigation revealed that the defect occurs inconsistantly and without any stimulus to the trigger.

Please advise me as to your preferred method of retribution for the dammages. I can be contacted at the following residence.

> Steve Moore 6206 Washtch Way Sacramento, Ca. 95842 332-3100

> > Sincerely,

Steve Moore