

**BARBER - Kinzer PPS GAL RE0003535**

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 06/26/92  
 ENTER REPAIR NUMBER -----> 9211322 15 39 41  
 7502256  
 FROM: (CUST NUM: 000093 ) MTVIEWSPOR MODEL: XP100  
 MT VIEW SPTS CTR INC GA/CAL: 223 REM  
 3838 OLD SEWARD HWY TYPE: FIREBALL  
 ACCESSORIES: SOFT CASE  
 ANCHORAGE AK 99503 SCOPE MNTS  
 SHIPPED TO: SCOPE BASE

DATE CODES: WU 8-71  
 OTHER ACCESSORIES:

COMMENTS: W/LEUPOLD M8-2X SCOPE  
 W/STUD & SWIVEL

DATES:		TO		FROM		
RECEIVED	05 01 92	GALLERY	00 00 00	00 00 00	00 00 00	ENTERED BY: FPS
OPENED	05 11 92	PROD SERV	00 00 00	00 00 00	00 00 00	REPAIRMAN: HB
ESTIMATED	06 01 92	TAG GUNS	00 00			TYPIST:
PROMISED	00 00 00	REJECTED	00 00			CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE:	N	
SHIPPED	06 02 92					

BILL TYPE N/C PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9211322 NO CHARGE EST/LETTER LSTD 06/26/92  
 CUSTOMER NAME: MT VIEW SPTS CTR INC 15 39 50

=====

REQUEST: GUN ACCIDENTLY DISCHARGED - SEE LETTER  
 MAIN FAULT: XP100 RECALL DONE-CHAMBER ALTERED OUT SIDE FACTORY  
 REPAIR TRIGGER UP DATE ONLY-BENCH TEST ONLY  
 PARTS: \$ 0.00 1 26790 SEAR HOUSING ASSEMBLY

REPAIRMAN'S INITS: HB NUM OF WKS: 03 CORRESPONDENT'S INITS:  
 TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE  
 NO MORE DATA AVAILABLE FOR THIS REPAIR